# Assistance Program

## Work Order (Bid Form)

#### WORK ORDER INFORMATION

L	No	rk	0	rde	r N	am	6
y	<b>,</b> , ,	71 N	$\mathbf{v}$	ue	, ia	alli	C.

Work Order Type: Weatherization

Audit Name: MADISON

#### **CLIENT INFORMATION**

Client Name:

Client ID:

Alt. Client ID: 16016SW-1010

Agency: SWHRA

<u>AGENCY INFORMATION</u>

Address: 1574 White AVE

Henderson, TN

Agency Contact: Murley, Rickey

**Agency Phone:** (731) 989-5111

Fax:

Email Address:

Work Phone:

Address: . .

Cell Phone:

Email Address:

Company Name & Licens	e Number:		
Contractor's Signature:			

#### COMMENT

NOTICE:

All work performed and material must meet all requirements as stated in the Southeast Weatherization Field Guide. It is the contractor's responsibility to pull all necessary permits required for the town or county where the work is being performed. No change order work shall be done until the change order has been approved and signed. If heater is required no air sealing should be done before heater is installed.

731-935-2003

Client Name: Client ID

Alt. Client ID: 16016SW-1010

Work Order (Bid Form)

Work Order Name:

Report Run On: 5/21/2010

DOE Weatherization Assistant

Version 8.5.0 Page 1 of 5

### Measures

ı	Measure 1 Infilt	ration Redctn			Componen	ts		ı	nspected
C	omment								
				,pgqqqqqqq	Estimated	***************************************		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Construction Materials/Hardwar e	Seal under kitchen sink,Seal pipes under all vanities.Seal behind washer and dryer and hole by plumbing box	Each	1					
2	Labor	Labor	Hour						
3	Construction Materials/Hardwar e	Seal exhaust vent over cook stove.Seal door that goes upstairs	Each	1					
4	Labor	Labor	Hour		The state of the s				
5	Construction Materials/Hardwar e	Weather-Strip D1,D2 and D3 door	Each	1				, , , , , , , , , , , , , , , , , , ,	
6	Labor	Labor	Hour		Tara transmission		0		
C	Other Detail				1		1		
					and the second		]		
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								

Measure 2 DW	VH Pipe Insulation			Component	ts		I	nspected	
Comment									
				Estimated		Actual			
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1 Insulation	DHW Pipe Insulation	Each	1						
2 Labor	Labor	Each	1						
Other Detail			,		, , , , , , , , , , , , , , , , , , ,	,			
			Measur	e Sub Total:			Sub Total:		
F*. / / \$/. /									
Field Notes:									
	/H Tank Insulation			Component	ts			nspected	
Measure 3 DW Comment				Estimated			Actual		
Measure 3 DW Comment # Material / Labor	Description / Comment	Units	Qty	-	ts Total	Qty		Inspected Total	
Measure 3 DW Comment		<i>Units</i> Each		Estimated		Qty	Actual		
Measure 3 DW Comment  # Material / Labor 1 Hot Water	Description / Comment		Qty	Estimated		Qty	Actual		
Measure 3 DW Comment  # Material / Labor 1 Hot Water Equipment	Description / Comment  DHW Tank Insulation	Each	Qty 1	Estimated		Qty	Actual		
Measure 3 DW Comment  # Material / Labor  1 Hot Water Equipment  2 Labor	Description / Comment  DHW Tank Insulation	Each	Qty 1	Estimated		Qty	Actual		
Measure 3 DW Comment  # Material / Labor  1 Hot Water Equipment  2 Labor	Description / Comment  DHW Tank Insulation	Each	Qty 1	Estimated			Actual		
Measure 3 DW Comment  # Material / Labor  1 Hot Water Equipment  2 Labor	Description / Comment  DHW Tank Insulation	Each	Qty 1 1	Estimated			Actual		
Measure 3 DW Comment  # Material / Labor  1 Hot Water Equipment  2 Labor	Description / Comment  DHW Tank Insulation	Each	Qty 1 1	Estimated Unit Cost			Actual Unit Cost		
Measure 3 DW Comment  # Material / Labor 1 Hot Water Equipment 2 Labor Other Detail	Description / Comment  DHW Tank Insulation	Each	Qty 1 1	Estimated Unit Cost			Actual Unit Cost		

Work Order (Bid Form)

	Measure 4 Atti	c Ins. R-30			Componen	ts A1			Inspected
C	omment								
					Estimated		***************************************	Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Attic Insulation - Blown Cellulose - R-30	SqFt	2316					
2	Labor	Labor	Hour	2316					
3	Construction Materials/Hardwar e	Install attic access cover	Each	1				The state of the s	
4	Labor	Labor	Hour						
C	Other Detail		,	,					
				Measure	e Sub Total:			Sub Total:	
		Monitor is Needed	-		Component	ćs			Inspected
C	omment				Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Health and Safety Items	CO monitor	Each	1			_	(LANALATATA)	
2	Labor	Labor	Hour	1					
0	ther Detail			<del></del>	r		p-1		
			ı	Measure	e Sub Total:		S	Sub Total:	
	Field Notes:								

Client Name:

Client ID:

Alt. Client ID: 16016SW-1010

Work Order (Bid Form)

Work Order Name:

Report Run On: 5/21/2010

Page 4 of 5

Me	asure 6 Pres	sureRelief Piping Nee	eded		Componen	ts			Inspected
Con	nment				Estimated			Actual	
# Ma	aterial / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
	ealth and Safety	Pressure relief piping	Each	1					, , , , , , , , , , , , , , , , , , , ,
2 La	abor	Labor	Hour	1					
Othe	er Detail		<u></u>		) [		7	1	
							<u> </u>		
	A			Measur	e Sub Total:			Sub Total:	
Fie	eld Notes:								
	R49		4		C				Inspected
		alce broke glass on E	1 Window		Component	S		•	mspected
Com	nment				Estimated			Actual	<u></u>
# Ma	aterial / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
	onstruction aterials/Hardwar	Misc Material	Each	1					
2 La	abor	Labor	Hour						
Othe	er Detail								
								Transcription of the state of t	
			I	Measur	e Sub Total:			Sub Total:	
Fie	eld Notes:								
									1

Client Name:

Work Order (Bid Form)

DOE Weatherization Assistant

Client ID:

Alt. Client ID: 16016SW-1010

Work Order Name:

Report Run On: 5/21/2010

Version 8.5.0 Page 5 of 5